



## Calapooia Watershed Council

PO Box 844 / 136 Spaulding Ave / Brownsville OR 97327  
541-466-3493 / [www.calapooia.org](http://www.calapooia.org)

### OWEB Grant #212-3999-9835 Completion Report Cox Creek Restoration Photos



**Figure 1. Albany City Councilors and Mayor, Parks Staff, MMT Program Director, CWC Board Members, Staff, and Contractors. Cox Creek Tour, fall 2013.**



**Figure 2. Attendees from the Willamette River Relay, Benton SWCD, TNC, and OPRD tour Cox Creek, summer 2014.**



**Figure 3. Cox Creek Confluence vegetation photo point - BEFORE.** Post flail mow, pre reed canarygrass spray, summer 2012.



**Figure 4. Cox Creek Confluence vegetation photo point - AFTER.** Post site prep, planting, and 2 seasons of plant establishment, summer 2014.



**Figure 5. Cox Creek Photo Point - BEFORE. Post flail mow, pre reed canarygrass spray, summer 2012.**



**Figure 6. Cox Creek Photo Point - DURING. Post reed canarygrass spray, during bareroot planting, March 2013.**



**Figure 7. Cox Creek Photo Point - AFTER. Post planting, after 2 seasons of plant establishment, summer 2014.**



**Figure 8. Cox Creek Photo Point - BEFORE. Post reed canarygrass flail mow, pre spray and pre planting, summer 2012.**



**Figure 9. Cox Creek Photo Point - DURING. Post planting, first year of plant establishment, summer 2013.**



**Figure 10. Cox Creek Photo Point - AFTER. Post planting, 2nd year of plant establishment, summer 2014.**